










N1  L=35 mm x8	M1  12x15 mm x8	A1  ZP x4	S1  3,5x16 mm x8	E1  8x30 mm x8	V13  x 1	
Z1  x80	F1  7x50 mm x8	S11  4x30mm x4	K3  x1	K7  5x16 mm x8	U1  L=190/160 x2	T1  x4



1	x	1
2	x	1
3	x	2
4	x	1
5	x	1
6	x	1
7	x	1
8	x	1
9	x	2

N1


K7



L=35 mm

x4

5x16 mm

x4


K7



N1



1



N1


K7



L=35 mm

x4

5x16 mm

x4


K7



N1



2



E1






8x30 mm



x4

M1



12x15 mm


x4**x2**



T1





x4



F1

K3




7x50 mm

x8

x1

F1

K3



F1


K3

4

Z1






x80













6

8 mm



X=Y





U1  x2	S11  4x30mm x4	V13  x 1
---	---	--

