

SKU:SF001074-2



BOARD IDENTIFICATION



So quantity * 2

Trouble Shooting

Missing/Damaged pieces/
Wrong size and installation issues

↓

Contact us with your problem,pic, number and qty to the "Contact seller" button in the detail page of your order

↓

Respond with 24 hours to solve issue

Before You Start

1.Read through each step carefully and follow the proper order


2.Separate and count all your parts and hardware


3.Give yourself enough room for the assembly process


4.Caution: If using a power drill or power screwdriver for screwing, please be aware to slow down and stop when screw is tight. Failure to do so may result in stripping the screw


Cam Lock Fastening System

This Cam Lock Fastening System willl be used throughout theassembly process

























Parts List

			
1 2PCS	2 2PCS	3 2PCS	4 2PCS
			
5 2PCS	6 4PCS	7 2PCS	8 8PCS
			
9 4PCS	10 4PCS	11 2PCS	12 2PCS
			
13 4PCS	14 4PCS	15 4PCS	16 4PCS

Hardware List



M6*35mm

A	100PCS



φ15*9mm

B	100PCS



M8*30mm

C	32PCS




Ø4*40mm

D	16PCS



M3*14mm

E	8PCS




F	8PCS




M3*12mm


G	40PCS




H	4PCS




I	4PCS



J	4PCS



K	4PCS




L	4PCS





M6*30mm


M	8PCS


STEP 1



M6*35mm
A
x100



M8*30mm
C
x32






A*6
4
X2
C*4



A*6
5
C*4
X2



A*4
8
X8



A*2
1
C*4
X2


A*2
3
X2



A*6
3
C*4
X2



A*4
11
X2



A*2
9
X4


A*4
12
X2


STEP 2



φ15*9mm
B
x16



8
B*4
4
8
X2



8
B*4
5
8
X2


STEP 3



L
I
x4


R
J
x4


M3*12mm
G
x16


8
G*2
I
G*2
I
4
8
X2


G*2
8
G*2
J
J
5
8
X2



I(L)
J(R)


STEP 4




φ15*9mm

B	x8






STEP 5




φ15*9mm


B	x16




STEP 6

φ15*9mm	M6*30mm
B x4	M x8







STEP 7




STEP 8






X2


STEP 9






X2


STEP 10




B	x12



E	x8




F	x8




X2


STEP 11



D	x16





X4




X4


STEP 12










STEP 13












STEP 14






X2



X2

STEP 15



X2

