







CAUTION:When tightening the screws,tighten sequentially.
Do not tighten any screws fully and then towards the next one.
When every part is OK,then tighten all the screws.













2 PERS.



Version: 1.0

1 Hardware List


A	16+2PCS	B	8PCS	C	8PCS	D	16+2PCS	E	12+2PCS
									
M6*35mm		15*10mm		15*12mm		8*30mm		M6*25mm	
F	4PCS	G	2PCS	H	2PCS	I	1PC	J	18+2PCS
									
M6*35mm		4*20mm						3.5*12mm	
K	16+2PCS	L	1PC						
									
4*35mm		M4mm							

2 Parts List




							
①	2pcs	②	2pcs	③	1pc	④	2pcs
							
⑤	2pcs	⑥	1pc	⑦	2pcs	⑧	1pc
							
⑨	1pc	⑩	2pcs	⑪	2pcs	⑫	2pcs
				 CR		 DR	
⑬	2pcs	⑭	2pcs	CR	2pcs	DR	2pcs
 CL		 DL					
CL	2pcs	DL	2pcs				



STEP 1







STEP 2



X2


STEP 3



X2

STEP 4


J 3.5*12
x8



X2

STEP 5


J 3.5*12
x8




X2

STEP 6

A 6*35 x4
C 15*12 x4
D 8*30 x4




STEP 7




STEP 8

K	4*35	D	6*30
			
	x4		x4




STEP 9


A	6*35	C	15*12	D	8*30
	x4		x4		x4





STEP 10



STEP 11




STEP 12




STEP 13

E	M6*25	J	3.5*12	I	
	x4		x2		x1



STEP 14



STEP 15

