




ASSEMBLY INSTRUCTIONS

- (A) 3.5x20=16x
- (B) 3.5x40=12x
- (C) 3.5x25=8x
- (D) 3.0x16=2x
- (E) + M4x50=4x
- (F) + M4x35=2x
- (G) 4x
- (H) 3.5x50=2x




1



(B) x8


2



Step x2


- (D) x2
- (B) x4
- (A) x16
- (G) x4

3



- (F) x2
- (E) x4
- (H) x2

4



(C) x8

