







Product Usage Instructions




INSTALLATION GUIDE




Suggest using electric tools for installation


SKU:16036S















SKU:16037S




SKU:16038S








A		65 PCS	M	 M50	1 PCS
B	 M15	65 PCS	O	 O-1 O-2	2 PCS
C	 80*80	6 PCS	P		1 PCS
D	 M8*40	13 PCS	Q		6 PCS
E	 M4*30	25 PCS	R	 M6*13	25 PCS
F	 M3.5*14	130 PCS	S	 M6*18	8 PCS
H	 M4*12	8 PCS	T	 T00L	1 PCS
I		4 PCS	W		2 PCS
J	 J-1 J-2	2 PCS	X	 M15*150	4 PCS
K		12 PCS	Z		2 PCS
L		8 PCS			

Special hardware install instructions






Special hardware removal instructions




A		8 PCS	D		4 PCS
B	 M15	8 PCS			


STEP 3




P		1 PCS	F	 M3.5*14	2 PCS
C	 80*80	2 PCS	R	 M6*13	8 PCS
A		10 PCS	D		4 PCS



STEP 4




A		4 PCS	B	 M15	14 PCS
---	---	-------	---	--	--------

STEP 5





F	 M3.5*14	10PCS	O	 O-1	2 PCS
Q		6 PCS			


STEP 6



7/16


A		10 PCS	B	 M15	10 PCS
F	 M3.5*14	8 PCS	O	 O-2	2 PCS
D		4 PCS	J	 J-2	2 PCS


STEP 7




A		2 PCS	B	 M15	2 PCS
F	 M3.5*14	6 PCS	K		3 PCS


STEP 8




A		6 PCS	B	 M15	6 PCS
---	---	-------	---	--	-------


STEP 9




A		2 PCS	B	 M15	2 PCS
F	 M3.5*14	6 PCS	K		3 PCS


STEP 10




A		6 PCS	B	 M15	6 PCS
---	---	-------	---	--	-------


STEP 11



E	 M4*30	8 PCS	K		6 PCS
---	--	-------	---	---	-------

F	 M3.5*14	12 PCS
---	--	--------

STEP 12




E



8 PCS

STEP 13




E




8 PCS

STEP 14




H	 M4*12	2 PCS	W	 	2 PCS
S	 M6*18	8 PCS			

STEP 15



H	 M4*12	4 PCS	I	 	4 PCS
C	 80*80	2 PCS	R	 M6*13	8 PCS

STEP 16



C



80*80

2 PCS


R





M6*13

8 PCS




STEP 17






STEP 18




STEP 19




F	 M3.5*14	80 PCS	L		8 PCS
X	 M15*150	4 PCS	STEP 20		



F	 M3.5*14	4 PCS	J	 J-1	2 PCS
Z		2 PCS			

STEP 21



STEP 22

