




ASSEMBLY INTRODUCTION











x2



Exploded View



Fitting



 Ax58(+2) Ø6x35mm	 Bx58(+2) Ø15x10mm	 Cx52(+2) Ø6x30mm	 Dx50(+2) Ø4x35mm	 Ex72(+2) Ø3.5x12mm
 Fx16	 Gx2	 Hx4 Ø3.5x12mm	 Ix16(+1) Ø3x16mm	 Jx4 Ø4x14mm
 Kx4 Ø6x30mm	 Lx8(+2)			
 CLx6 L300mm	 CRx6 L300mm	 DLx6 L300mm	 DRx6 L300mm	

Step 1




x6

Step 2




x6



Step 3



Step 4




Step 5




Dx4

x2

Step 6




Bx6



Cx6

x2


Step 7



Bx6






Cx6



Dx4

x2


Step 8




Ax8

x2

Step 9




Bx8




Cx8

x2

Step 10






Cx16



Fx16



x2

Step 11





x2

Step 12




x2

Step 13





x2

Step 14







x2

Step 15





x2

Step 16



x2






Step 17



Lx8

x2

Step 18



x2