














ASSEMBLY INSTRUCTION








PART LIST

1		2		3	
	1PC		1PC		1PC
4		5		6	
	1PC		1PC		1PC

HARDWARE LIST


A	B	C
		
7 PCS M $\frac{1}{4}$ 'X35	12 PCS M $\frac{1}{4}$ 'X15	1PC M4X23X57

STEP 1

B


M₄¹ x 15

4 PCS





STEP 2

B





M₄¹ x 15

4 PCS



STEP 3

A	B
 M $\frac{1}{4}$ "x35	 M $\frac{1}{4}$ "x15
7 PCS	4 PCS



60%