

Tools Recommended

EN_IMPORTANT, RETAIN FOR FUTURE REFERENCE: READ CAREFULLY.












FR_IMPORTANT: A LIRE ATTENTIVEMENT ET À CONSERVER POUR CONSULTATION ULTÉRIEURE.







ES_IMPORTANTE, LEA Y GUARDE PARA FUTURAS REFERENCIAS.

PT_IMPORTANTE, RETER PARA REFERÊNCIA FUTURA: LEIA ATENTAMENTE.


















DE_WICHTIG! SORGFÄLTIG LESEN UND FÜR SPÄTER NACHSCHLAGEN AUFBEWAHREN.

IT_IMPORTANTE! CONSERVARE IL PRESENTE MANUALE PER FUTURO RIFERIMENTO E LEGGERLO ATTENTAMENTE.

BOX 1/2	 P
 E	 Q*2
 F	 R*4
 H*2	 Hardware Kit
 J*3	
 K	
 L	
 M*2	
 N*2	
 O	

BOX 2/2	
 A	
 B	
 C	
 D	
 G	
 I	



PARTS

		
A	B	C
		
D	E	F
		
G	H*2	I
		
J*3	K	L
		
M*2	N*2	O
		
P	Q*2	R*4


HARDWARE

			
5.0*45mm 20pcs	3.5*25mm 28+2pcs	3.5*20mm 4pcs	3.5*15mm 12+1pcs
S1	S2	S3	S4
			
3.0*18mm 19+1pcs	2.0*10mm 12+1pcs	2pcs	
S5	S6	S7	



01

O x01**P** x01**Q** x02**S5** x07


3.0*18mm



02



A x01**B** x01**E** x01**S1** x06

5.0*45mm




03

02

**C** x01**D** x01**S1** x02

5.0*45mm




04


03

**F** x01**S1** x06


5.0*45mm




04

**G** x01**S1** x04

5.0*45mm



S1*4**G**

05



**I** x01**M** x02**S2** x12

3.5*25mm

M*2**S2*8****S2*4****I**

K x01**L** x01**S1** x02

5.0*45mm

**06****07****J** x03**S2** x12

3.5*25mm

S2*12**J*3**

