


Playhouse Swing

Assembling Instruction BSLFOT161GN













ATTENTION

Thanks for choosing our product.

There will be 2 boxes in total for this whole product.

(We will hand over all the boxes to the logistics provider together, but they may transport them separately, which may result in inconsistent arrival times of the boxes.)

PARTSLIST (BOX A)


	1 x1		2 x1		6 x1
	10 x1		11 x1		12 x1
	13 x4		15 x1		16 x1
	17 x1		18 x2		21 x4
	22 x1		23 x1		26 x2
	27 x1		28 x1		29 x3
	30 x2		31 x3		32 x1
	34 x1		38 x1		40 x1
	41 x1		42 x2		43 x1

PARTSLIST (BOX B)

3 x1



4 x1




4-1 x1




5 x2



6 x2




7 x1



8 x1




9 x1




14 x1



19 x1




20 x1




24 x2



25 x1




35 x1



36 x1












37 x1












39 x1



PARTSLIST (BOX A)


A x55 M4x30 	B x26 M6x60 	C x13 M6x50 	D x11 M6x40 
E x 1 M4x60 	F x 11 M4x50 	G x 8 M4x40 	H x 2 M6x20 
I x 2 	J x5 M4x25 	K x2 M6x55 	L x1 
M x6 M6x30 	N x4 	O x10 	P x 2 
Q x5 M8x30 	R x8 M6x25 	S x71 	T x4 
U x16 M6x70 	V x4 	W x1 	






01



Q x 1
M6x30



02




F x 1
M4x50



U x 4
M6x70




S x 4



B x 4
M6x60



S x 4





U x 4
M6x70



S x 4



U




The nut is facing inward

(B) x 4
M6x60




(S) x 4



(B) x 4
M6x60




(S) x 4



B x 4
M6x60




S x 4



U x 4
M6x70




S x 4



U x 4
M6x70



S x 4



U

U

S

The nut is facing inward

9

U

S


C x 2
M6x50





D x 2
M6x40



S x 2



A x10
M4x30





D x 1
M6x40





S x 1





E x 1
M4x60



A x15
M4x30



A x12
M4x30




B x 4
M6x60



S x 4



The nut is facing outward




(B) x 4
M6x60



(S) x 4



The nut is facing outward




(D) x 2
M6x40



(S) x 2



(F) x 2
M4x50





D x 2
M6x40




S x 2



F x 2
M4x50





F x 2
M4x50



D x 2
M6x40




S x 2






D x 2
M6x40




S x 2







F x 2
M4x50



D x 1
M6x40




S x 1





D x 1
M6x40



S x 1




G x 4
M4x40





The long hole spacing
is on this side



G x 4
M4x40





A x 2
M4x30





A x 4
M4x30





A x 6
M4x30







A x 4
M4x30



A x 2
M4x30







C x 2
M6x50





O x 2



L x 1




N x 4



C x 2
M6x50



O x 2





K x 2
M6x55



O x 2




P x 2



M x 4
M6x30




O x 4



J x 3
M4x25



S x 3



B x 2
M6x60




M x 2
M6x30





S x 4





I x 2




J x 2
M4x25



T x 4**R** x 8
M6x25**S** x 8**V** x 1

H x2
M6x20



H

43

