


INSTALLATION INSTRUCTIONS

PARTS LIST



Right-angle connector




Self-tapping screw

The extra parts are for spare


STEP 1

Lay the tabletop upside down on the floor and place the table legs as illustrated.



STEP 2

Fasten table legs using self-tapping screws; mount right-angle connectors at joints of box-shaped table legs.



Secure with self-tapping screws.

STEP 3

Feed the power plug through the internal holes, then install the power outlet on the tabletop.

