
20 x 20 FT



Attention:

Please read the manual completely before starting the installation(A ladder & an electric drill are recommended for the assem-bly.)

1. Please confirm that the parts are complete and undam-aged.(Corresponding part number is affixed to each part) If any parts are missing or damaged, please contact the cus-tomer support email to reissue or contact seller.

1.1 Please Contain: ① Order number ② Model number ③ Item Number @Photos of the missing/damaged parts(optional)

1.2 Steps to Contact seller:


Step 1: Log into your account


Step 2: Go to "Your Orders" and find the purchase

Step 3: Click on "Contact Seller"


Structural diagram

Arrange and classify the parts neatly to facilitate installation. This is the part structure diagram of our product, you can combine this diagram and follow the steps to install














* All the optional tools listed above are not included in this product.







PARTS LIST

1		6pcs	E		41pcs
1A		12pcs	F	 M6×45	40pcs
2		5pcs	G	 M8×80	30pcs
2A		20pcs	H	 M8×50	24pcs
3		12pcs	I	 M8*50	4pcs
4		8pcs	J	 M8×75	12pcs
4A		4pcs	K		4pcs
5		10pcs	L	 ϕ 4.5×170	24pcs
6		6pcs	M		1pc
7		4pcs	N		2pc
A		8pcs	O	 M6/M8	2pc
B		16pcs	P	 M8*60mm	24pcs
C		12pcs			2pcs


1


1
1
2A
1
2A
1
2A
1
2A
2
1
G
2
1
G
2A
1
2


2


1
1
2A
6
1A
1
2A
6
1A
1
2A
6
1A
1
2A
6
1A
2
6
1
1A
6
1A
1A
1A
1A
1
J
6
1A


3




4




5




6




7




8




9




10




11




12



13



14



Securing Ratchet Tie-Downs

Note: Use these instructions in the pages that follow.

1. Thread the strap through the Ratchet's (K) spindle as far as it will go.




Figure K: Threading Strap through Spindle

2. Insert the S-hook of the Ratchet into the hole in the Corner Leg (I).




Figure L: Inserting Hook into Corner Leg

3. Lift and lower the Ratchet's handle to wind and tighten the strap onto the spindle.




Figure M: Tightening Ratchet

NOTICE: Excessive tightening will damage straps, Covers, and Corner Legs.

Releasing Ratchet Tie-Downs

1. Depress the spring-loaded bar on the handle.
2. Open Ratchet handle completely.
3. Unwind the strap.







Figure N: Releasing Ratchet


15



16







when it is used on concrete/cement floor

