



ASSEMBLY INTRODUCTION



Exploded View



Fitting



A x 50
M6 x 35 mm



B x 50
φ15 x 9.5 mm



C x 22
φ6 x 30 mm




D x 13
φ4 x 35 mm




E x 24
φ3 x 12 mm




G x 2



H x 12
φ3 x 14 mm



I x 2
φ4 x 40 mm




J x 3
φ6 x 50 mm



K x 4
φ35 mm



L x 48
φ3.5 x 12 mm



M x 4
φ35 mm




CL x 2
350 mm



CR x 2
350 mm




DL x 2
350 mm




DR x 2
350 mm



Step 1





Step 2





Step 3




Step 4




Step 5







Step 6




Step 7




Step 8





Step 9





Step 10




Step 11





Step 12





Step 13





Step 14




Step 15



Step 16



Step 17



K x 4
φ35 mm




L x 16
φ3.5 x 12 mm




M x 4
φ35 mm


Step 18




L x 32
φ3.5 x 12 mm




Step 19





Step 20




Step 21



Step 22





Step 23




x2




Step 24



x2



Step 25



Step 26

