


















PART LIST:			
①  1PC	②  1PC	③  1PC	④  1PC
⑤  1PC	⑥  1PC	⑨  1PC	⑩  1PC
⑪  2PCS	⑫  4PCS		

HARDWARE LIST:			
A  M8×20 16PCS	B  M8×55 5PCS	C  22PCS	D  17PCS
E  2PCS	F  4PCS	G  6PCS	L  1PC
I  1PC	J  M8×30 12PCS	K  M8×80 2PCS	


Step 1



Step 2




Step 3




A	 x8
---	--

Step 4




F	 x4
---	--

Step 5



Step 6



Step 7

