
BED FULL
ASSEMBLY INSTRUCTIONS







Attention

Please use the screws correctly according to the instructions.
Thank you.



Part List


5
4
17
12
14
14
14
14
14
14
14
14
15
9
14
14
14
14
14
4
6
19
14
14
14
13
12
24
16
8
22
2
3
1
1
7
11
23
18
10
3
18
23
20
21


Parts view

1-2pcs	2-1pcs	 3-2pcs	 4-2pcs
 5-1pcs	 6-1pcs	 7-1pcs	8-1pcs
9-1pcs	10-1pcs	11-1pcs	12-2pcs
 13-1pcs	14-16pcs	15-1pcs	16-1pcs
17-1pcs	18-2pcs	19-1pcs	 20-1pcs
 21-1pcs	22-1pcs	 23-2pcs	 24-1pcs

Hardware List


 A M6*55mm--28PCS	 B M6*50mm--19PCS	 C M6*35mm--17PCS	D M6*32mm--4PCS	E M6*12mm--2PCS
 F M6*17mm--20PCS	 G 4mm--4PCS	 H 2PCS	 I 3mm--1PCS	 J 4PCS
 K 2PCS	 L 4*35mm--2PCS	 M 4*12mm--2PCS	 N 4*30mm--4PCS	 O M5*60--1PCS
 P M5*35--1PCS	R Light strips--1PCS	S Socket--1PCS		

Step 1




Attention

The side holes of components 11 & 16 & 17 should face inward




A	C	G		
M6*55mm--8PCS	M6*35mm--6PCS	4mm--1PCS		

Step 2




C M6*35mm--5PCS	F M6*17mm--1PCS	G 4mm--2PCS		

Step 3




 A M6*55mm--3PCS	 C M6*35mm--1PCS	 G 4mm--1PCS		

Step 4




 A M6*55mm--8PCS	 E M6*12mm--2PCS	 G 4mm--1PCS		

Step 5




 A M6*55mm--4PCS	 G 4mm--1PCS			


Step 6




 A M6*55mm--2PCS	 C M6*35mm--4PCS	 G 4mm--1PCS		

Step 7




 A M6*55mm--2PCS	 G 4mm--1PCS			

Step 8




				
D M6*32mm--4PCS	O M5*60mm--1PCS	P M5*35mm--1PCS	G 4mm--1PCS	I 3mm--1PCS


Step 9




M 4*30mm--4PCS				

Step 10






				
B M6*50mm--8PCS	F M6*17mm--8PCS	G 4mm--2PCS		

Step 11





Step 12




 B M6*50mm--10PCS	 F M6*17mm--10PCS	 H 2PCS	 G 4mm--2PCS	

Step 13




 M 4*12mm--2PCS	 R Light strips--1PCS	 S Socket--1PCS		

Completed



Tips:
If you feel that the bed is a little wobbly then please use the parts "K"&"L" for reinforcement



Please tighten all screws before use, thank you.