

Assembly Instruction-5037D

A X1



B X2



C X2



D X4



M6X 16mm

E X4




M6X 30mm

F X1




Spanner

Step 1



Step 2



Finish

