



WF322318
WF322319



ASSEMBLY INSTRUCTIONS




PARTS

Check that you've received
all parts listed below.


BOX: 1/2
WF322318

1 x 1




Head Board

5 x 1



Leg Board Left

6 x 1



Leg Board Right

7 x 2



Legs

8 x 6



Slats

9 x 4




Slats

8 x 4



Support Legs

Hardware



PARTS

Check that you've received
all parts listed below.

BOX: 2/2
WF322319

2 x 1



Side Board Left

3 x 1



Side Board Left

4 x 1




Foot Board

HARDWARE


Check that you've received
all hardware listed below.

Hardware List

No.	OUTLOOK	DESC	QTY
A		Bolts 5/16"x50 mm	8
B		Bolts 5/16"x40 mm	2
C		Bolts 5/16"x30 mm	8
D		Plain washer Ø19x1.5 mm	18
E		Spring washer Ø13x1 mm	18
F		Allen key 80x30x4 mm	1
G		Screws Ø4x30 mm	20


STEP 1

A x 8 	D x 8 	E x 8 	F x 1 	
--	--	--	--	--




STEP 2

B x 2 	D x 2 	E x 2 	F x 1 	
--	--	--	--	--




STEP 3

C x 4	D x 4	E x 4	F x 1	
				






STEP 4




C x 4	D x 4	E x 4	F x 1	
				



STEP 5



STEP 6



STEP 7

G x 20

