





A M6*35mm




x28

B M15*10mm




x28

C M6*30mm



x20

D M3.5*14mm




x2

E M4*30mm




x4

F M5*38mm




x4

G




x2

H




x1

I



x1

J



x1


K

M4*22mm




x2

L




x2

M M4*35mm



x2

N M4*12mm




x20

O



x2

P




x1

Q



x1


R




x8



S

M3.5*16mm




x8







STEP 1





STEP 2





STEP 3




STEP 4



STEP 5




STEP 6




B	C
 x4	 x2

STEP 7




B	C
 x4	 x4


STEP 8



STEP 9




STEP 10





B	C
 x8	 x4

STEP 11




R	S
 x8	 x8

STEP 12




M  x2	O  x2
	N  x4



STEP 13





STEP 14



STEP 15



STEP 16



STEP 17

