














Assembly Instruction




PACKING DETAILS




Hardware List

A  6 x 35 mm	B  Ø12 x 10 mm	C  Ø6 x 30 mm	D  M3.5 x 12 mm
30+2 pcs	30+2 pcs	30+3 pcs	26+2 pcs
E  8+1 pcs	F  4 pcs	G  4 pcs	H  M3.0 x 16 mm 4 pcs
8+1 pcs	4 pcs	4 pcs	4 pcs
I  6+1 pcs	J  2 pcs	K  1 pc	L  1 pc
6+1 pcs	2 pcs	1 pc	1 pc
CR  2 pcs	CL  2 pcs	DR  2 pcs	DL  2 pcs
2 pcs	2 pcs	2 pcs	2 pcs

STEP 1






CRx2




Dx4



Ax2



STEP 2




Bx2




Cx2




STEP 3




Ax8



STEP 4




Ix2




Cx2



STEP 5





Ix4




Cx4




STEP 6





CLx2




Dx4



Ax12



STEP 7




Bx5




Cx6



STEP 8



STEP 9




Bx7



Cx8



STEP 10




Bx8




Cx8



STEP 11




Dx8



Fx4



STEP 12




Hx4




Gx4



STEP 13




Ex8




X2

STEP 14



X2

STEP 15





Jx2



Bx8




Ax8




X2


STEP 16




DR




DL




DRx2



DLx2





Dx8




X2


STEP 17



STEP 18



Dx2



Kx1

