# How to self-clean when the LED does not light up well? (For Handheld Shower)

**Step 1:**

Allen Wrench

Insert the Allen Wrench Into the bottom of the handheld shower.

Step 2:

Connector

Remove the Connector by turning the Allen Wrench counter-clockwise.

**Step 3:**

Turbo   Generator Cover

Remove the Generator Cover. Clean the Turbo and turn the Turbo a couple turns.

Step 4:

Put the Generator Cover back.

Step 5:

Screw the Connector back.