



BED FRAME



Thank you for choosing our products, please assemble and use it following the instructions.

Assembly Instruction






Important Note

HARDWARE NOTE :



1. Two or more people are required for assembly
2. Do not screw on the bolts too tight unless the installation is done. Make sure all bolts are tightly screwed before you use it.

Exploded view diagram of the 10 components for the 3D printer frame, numbered 1 through 9. Each component is shown with its corresponding quantity:


- 1 x4pcs
- 2 x4pcs
- 3 x2pcs
- 4 x1pc
- 5 x2pcs
- 6 x1pc
- 7 x2pcs
- 8 x1pc
- 9 x2pcs





2




3



4




5



C		4pcs
---	---	------


6



C		4pcs
---	--	------

7


x2







A		16pcs
---	---	-------

8


x2



D		16pcs	White Zinc
---	--	-------	------------




13




D		2pcs	White Zinc
E		2pcs	

14




B		4pcs	White Zinc
---	---	------	------------


15



D		2pcs	White Zinc
E		1pcs	

16





Note: Now you can tighten all the bolts.

Finish