


Height-Adjustable Desk Assembly Instructions




First, secure the lifting bracket to the desk leg as shown in the figure.



Place the desktop in position. Take care not to pinch the wires.





Insert each cable into the corresponding port of the control box in sequence.




Check whether the lifting function of the device operates normally.




Align the crossbar with the screw holes underneath the desktop and fasten securely.







Next, insert the drawer into its matching position on the tabletop.



Fasten the screws on both sides of the drawer.



Connect the light-strip switch with its matching cable.



Check whether the light strip functions properly.



Finally, confirm that the desk can travel to both its maximum and minimum height. The installation is complete.