













ASSEMBLY INSTRUCTION





Loosely hand-tighten screws when fitting the table base; fully tighten all only after the full frame is aligned and assembled.

If you have any questions, please feel free to contact us at any time.

Parts & Tool List

<div>① x2</div> <div></div>	<div>② x1</div> <div></div>	<div>③ x2</div> <div></div>	<div>④ x4</div> <div></div>	<div>⑤ x2</div> <div></div>
<div>⑥ x2</div> <div></div>	<div>⑦ x2</div> <div></div>	<div>⑧ x1</div> <div></div>		
<div>A x16+1</div> <div></div> <div>M6*70mm</div>	<div>B x10+1</div> <div></div> <div>M6*60mm</div>	<div>C x6+1</div> <div></div> <div>M6*25mm</div>	<div>Dx12+1</div> <div></div> <div>M6*12mm</div>	<div>Ex2</div> <div></div> <div>S4</div>



1



× 2



Cx4
Bx4
Ex2

2



Dx4
Ex1



3



× 2


Dx8
Ex1

4






Ax8
Ex1


5




Screw holes face upward



Cx2




Bx2




Ex2

6






7

Notice: keep all the screws 50% tightness first , then Push the 1&2 desktop, make sure no gap , then tighten the screws




Push


Push



Ax8




Bx4



Ex1

8



9

