
ASSEMBLY INSTRUCTIONS




IMPORTANT NOTE:



















① PLACE ALL PARTS ON A CLEAN AND SMOOTH SURFACE SUCH AS A RUG OR CARPET TO AVOID THE PARTS FROM BEING SCRATCHED.

② BEFORE YOU BEGIN,KINDLY FOLLOW THE ASSEBLY INSTRUCTIONS STEP BY STEP.

③ DO NOT TIGHTEN ALL SCREWS AND BOLTS UNTIL THIS ITEM IS FULLY SET-UP.

Detail View


12
8
9
10
26
27
26
16
14
24
26
27
26
13
15
1
28
18
17
3
26
5
28
30
4
16
25
27
18
17
31
27
29
2
23
11
21
22
20
19
7
6

1 	2 	3 	4 
1pc	1pc	1pc	1pc
5 	6 	7 	8 
1pc	1pc	1pc	1pc
9 	10 	11 	12 
1pc	1pc	1pc	1pc
13 	14 	15 	16 
1pc	1pc	1pc	2pcs
17 	18 	19 	20 
2pcs	2pcs	1pc	1pc
21 	22 	23 	24 
1pc	3pcs	1pc	1pc
25	26	27	28
1pc	4pcs	4pcs	2pcs
29 	30 	31 	
1pc	2pcs	1pc	


Hardware List

A ⌀3.5*45 11pcs	B ⌀3.5*40 32pcs	C ⌀3.5*35 21pcs	D ⌀3.0*30 12pcs
E ⌀3.5*25 10pcs	F ⌀3.0*25 24pcs	G ⌀3.0*16 20pcs	H ⌀3.0*18 4pcs
I ⌀6.0*20 20pcs	J ⌀6.0*25 2pcs	K 23pcs	L 16pcs
M 2pcs	N 1pc	O 1pc	P 2pcs
Q 2pcs	R 1pc	S 4pcs	T 2pcs
U 4pcs	V 1pc		

ASSEMBLY TOOLS REQUIRED(NOT INCLUDED)

PLEASE BE CAREFUL DO NOT DAMAGE THE HOLE POSITION WHEN YOU USE POWERTOOLS !


C*16
K*16



C*16	K*16

Step 1


K*7



Step 2

K*7


B*4
C*2



Step 3

B*4	C*2


E*10
P*2
T*2



Step 4

E*10	P*2	T*2


A*11
C*1



Step 5

A*11	C*1


I*20
R*1
S*4



Step 6

I*20	R*1	S*4


F*6



Step 7

F*6


F*6



Step 8


F*6

B*4
J*2




B*4	J*2

Step 9




Step 10

G*2
N*1




G*2	N*1

Step 11



Step 12


B*12




Step 13

B*8

B*4




Step 14




B*4


L*16



Step 15




L*16



Step 16


Q*2



Step 17

	
Q*2	


D*6



Step 18

	
D*6	


D*6



Step 19

	
D*6	


G*8
M*2



Step 20

	
G*8	M*2


F*12



F*12

Step 21


G*6
H*4



G*6	H*4

Step 22


C*2



C*2

Step 23


G*4
O*1



Step 24

G*4	O*1

U*4
V*1



Step 25

U*4	V*1