






A x04




B x03




C x02




D x02




E x01




F x01




G x01




H x01




I x01




J x01



K x01




L x01




HARDWARE


M x14
M4*12
+1(spare)




N x14
M4*35
+1(spare)



O x06
M6*40
+1(spare)



P x04
M6*45



Q x04
M6




R x01
M10




S x04
M6*50



T x01
M4






M6*45


Q x04
M6



01






M x06
M4*12

02









N x02
M4*35

Done

