

























Assembly instruction



Assembly instruction




① x1 	② x1 	③ x1 
④ x2 	⑤ x4 	⑥ x1 
⑦ x5 	⑧ x1 	⑨ x1 
⑩ x2 	⑪ x1 	⑫ x14 
⑬ x2 	⑭ x1 	⑮ x1 
⑯ x1 	⑰ x1 	⑱ x1 
⑲ x1 	⑳ x1 	㉑ x1 
㉒ x1 	㉓ x1 	㉔ x1 


25 x1




26 x1




27 x2



28 x1



29 x2




30 x2




31 x1




32 x1




33 x1



34 x1












35 x1




36 x1



Hardware List

A×16 (1+extra)  M8×20mm	B×18(1+extra)  M6×55mm	C×29(2+extra)  M6×38mm
D×10 (1+extra)  M6×28mm	E×28 (2+extra)  M6×15mm	F×17 (1+extra)  M6×10mm
G×5 (1+extra)  M6×15mm	H×2  H-1  H-2 M4 M4	I×2 
J×2  M8×40mm	K×2  M5×40mm	L×2  M4×12mm

1



A×4pcs




M8×20mm

B×1pc




M6×55mm

2



B×2pcs



M6×55mm

D×1pc




M6×28mm

E×2pcs




M6×15mm

3



A×4pcs




M8×20mm

E×4pcs



M6×15mm

4




F×16pcs




M6×10mm


Step 1



Step 2



5





E×8pcs



M6×15mm

6




A×8pcs




M8×20mm


I×2pcs



7




B×4pcs






M6×55mm


D×4pc




M6×28mm




8



C×2pcs



M6×38mm




9

E×2pcs




M6×15mm




10


B×4pcs



M6×55mm




11



B×4pcs




M6×55mm




12

B×2pcs



M6×55mm




13


E×2pcs



M6×15mm




14



C×4pcs




M6×38mm




15


C×4pcs



M6×38mm




16





E×4pcs



M6×15mm



17




B×1pc



M6×55mm

C×1pc




M6×38mm

E×2pcs




M6×15mm

18




C×8pcs




M6×38mm


19



C×8pcs



M6×38mm




20

F×1pc




M6×10mm


Step 1




Step 2



21



D×3pcs



M6×28mm

E×4pcs




M6×15mm


G×5pcs



M6×15mm



22





23



L×2pcs




M4×12mm




24



25



C×2pcs




M6×38mm


D×2pcs



M6×28mm



26



J×2pcs



M8×40mm

K×2pcs



M5×40mm