



28



|   |                                                                                          |      |
|---|------------------------------------------------------------------------------------------|------|
| G |  ST4x14 | 2pcs |
|---|------------------------------------------------------------------------------------------|------|


29



|   |                                                                                   |       |
|---|-----------------------------------------------------------------------------------|-------|
| I |  | 48pcs |
|---|-----------------------------------------------------------------------------------|-------|

30


- 1: Using a drill bit with a diameter of 6, drill mounting holes where installation is required
- 2: Place the expansion tube into the hole
- 3: Screw the screw together with the mounting part into the expansion pipe



|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| Z |  | 2pcs |
|---|-------------------------------------------------------------------------------------|------|


Finish

31




Note: Now you can tighten all the bolts.

# BED FRAME



Thank you for choosing our products, please assemble and use it following the instructions.

Assembly Instruction




B438

Important Note

- HARDWARE NOTE :
- 1. Two or more people are required for assembly
  - 2. Do not screw on the bolts too tight unless the installation is done. Make sure all bolts are tightly screwed before you use it.


24



E M8x55 2pcs


Do not fully tighten the screws yet.

26




F M5x40 3pcs

25



F M5x40 6pcs

27



Fully tighten all the screws.

C M6x30 4pcs

20

|   |  |       |      |
|---|--|-------|------|
| D |  | M8x35 | 4pcs |
|---|--|-------|------|

Do not fully tighten the screws yet.

21

|   |  |       |      |
|---|--|-------|------|
| C |  | M8x30 | 4pcs |
|---|--|-------|------|

Do not fully tighten the screws yet.

Components

- 1 x2pcs
- 2 x2pcs
- 3 x3pcs
- 4 x4pcs
- 5 x24pcs
- 6 x10pcs
- 7 x2pcs
- 8 x7pcs
- 9 x1pc

- 10 x3pcs
- 11 x1pc
- 12 x1pc
- 13 x1pc
- 14 x1pc
- 15 x1pc
- 16 x1pc
- 17 x2pcs
- 18 x1pc
- 19 x1pc

22

|   |  |       |      |
|---|--|-------|------|
| A |  | M8x16 | 1pc  |
| D |  | M8x35 | 2pcs |

Do not fully tighten the screws yet.

23

|   |  |       |     |
|---|--|-------|-----|
| A |  | M8x16 | 1pc |
| D |  | M8x35 | 1pc |


Do not fully tighten the screws yet.

- 20 x1pc
- 21 x1pc
- 22 x1pc
- 23 x1pc
- 24 x1pc
- 25 x1pc
- 26 x1pc
- 27 x1pc
- 28 x1pc


- 29 x1pc
- 30 x2pcs
- 31 x1pc
- 32 x1pc
- 33 x1pc
- 34 x1pc
- 35 x3pcs
- 36 x1pc

- M8x16 • • • • • • • • • • **A** x11pcs
- M8x25 • • • • • • • • • • **B** x24pcs
- M8x30 white zinc • • • • • • • • • • **C** x8pcs
- M8x35 • • • • • • • • • • **D** x19pcs
- M8x55 • • • • • • • • • • **E** x54pcs
- M5x40 • • • • • • • • • • **F** x9pcs
- ST4x14 • • • • • • • • • • **G** x2pcs
- M8 • • • • • • • • • • **H** x2pcs
- • • • • • • • • • **I** x48pcs

- M8 • • • • • • • • • • **J** x1pc
- M5 • • • • • • • • • • **K** x1pc
- • • • • • • • • • **L** x1pc
- • • • • • • • • • **U** x1pc
- • • • • • • • • • **Y** x2pcs
- • • • • • • • • • **Z** x2pcs




|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| E |  | 2pcs |
| H |  | 2pcs |




|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| D |  | 4pcs |
|---|-------------------------------------------------------------------------------------|------|



TYPE 1



TYPE 1




TYPE 2




|   |                                                                                       |      |
|---|---------------------------------------------------------------------------------------|------|
| E |  | 2pcs |
|---|---------------------------------------------------------------------------------------|------|

**!** Do not fully tighten the screws yet.




|   |                                                                                       |      |
|---|---------------------------------------------------------------------------------------|------|
| E |  | 2pcs |
|---|---------------------------------------------------------------------------------------|------|

12



|   |                                                                                   |     |
|---|-----------------------------------------------------------------------------------|-----|
| E |  | 1pc |
|---|-----------------------------------------------------------------------------------|-----|


13



|   |                                                                                   |      |
|---|-----------------------------------------------------------------------------------|------|
| A |  | 4pcs |
|---|-----------------------------------------------------------------------------------|------|

1


x2



|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| D |  | 4pcs |
|---|-------------------------------------------------------------------------------------|------|


2

x2



|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| B |  | 4pcs |
| E |  | 4pcs |


14



|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| E |  | 4pcs |
|---|-------------------------------------------------------------------------------------|------|

⚠ Do not fully tighten the screws yet.


15



|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| E |  | 4pcs |
|---|-------------------------------------------------------------------------------------|------|

⚠ Do not fully tighten the screws yet.


3



|   |                                                                                       |      |
|---|---------------------------------------------------------------------------------------|------|
| E |  | 4pcs |
|---|---------------------------------------------------------------------------------------|------|

⚠ Do not fully tighten the screws yet.


4



|   |                                                                                       |      |
|---|---------------------------------------------------------------------------------------|------|
| E |  | 6pcs |
|---|---------------------------------------------------------------------------------------|------|

⚠ Do not fully tighten the screws yet.


5



⚠ Do not fully tighten the screws yet.

|   |                                                                                         |      |
|---|-----------------------------------------------------------------------------------------|------|
| A |  M8x16 | 3pcs |
| D |  M8x35 | 3pcs |

6




⚠ Do not fully tighten the screws yet.

|   |                                                                                         |      |
|---|-----------------------------------------------------------------------------------------|------|
| A |  M8x16 | 2pcs |
|---|-----------------------------------------------------------------------------------------|------|

8


x5



|   |                                                                                           |       |
|---|-------------------------------------------------------------------------------------------|-------|
| B |  M8x25 | 10pcs |
|---|-------------------------------------------------------------------------------------------|-------|


9

x2



|   |                                                                                           |      |
|---|-------------------------------------------------------------------------------------------|------|
| B |  M8x25 | 8pcs |
| E |  M8x55 | 8pcs |


7



|   |                                                                                           |     |
|---|-------------------------------------------------------------------------------------------|-----|
| D |  M8x35 | 1pc |
| E |  M8x55 | 1pc |


8

x5



|   |                                                                                           |       |
|---|-------------------------------------------------------------------------------------------|-------|
| B |  M8x25 | 10pcs |
|---|-------------------------------------------------------------------------------------------|-------|


10



|   |                                                                                             |       |
|---|---------------------------------------------------------------------------------------------|-------|
| E |  M8x55 | 12pcs |
|---|---------------------------------------------------------------------------------------------|-------|


⚠ Fully tighten all the screws.

11



|   |                                                                                             |      |
|---|---------------------------------------------------------------------------------------------|------|
| B |  M8x25 | 2pcs |
| E |  M8x55 | 2pcs |


4



⚠ Do not fully tighten the screws yet.

|   |                                                                                   |       |      |
|---|-----------------------------------------------------------------------------------|-------|------|
| E |  | M8x55 | 6pcs |
|---|-----------------------------------------------------------------------------------|-------|------|

5




⚠ Do not fully tighten the screws yet.

|   |                                                                                   |       |      |
|---|-----------------------------------------------------------------------------------|-------|------|
| A |  | M8x16 | 3pcs |
| D |  | M8x35 | 3pcs |


9

x2



|   |                                                                                     |       |      |
|---|-------------------------------------------------------------------------------------|-------|------|
| B |  | M8x25 | 8pcs |
| E |  | M8x55 | 8pcs |


10



⚠ Fully tighten all the screws.

|   |                                                                                     |       |       |
|---|-------------------------------------------------------------------------------------|-------|-------|
| E |  | M8x55 | 12pcs |
|---|-------------------------------------------------------------------------------------|-------|-------|


6



⚠ Do not fully tighten the screws yet.


|   |                                                                                     |       |      |
|---|-------------------------------------------------------------------------------------|-------|------|
| A |  | M8x16 | 2pcs |
|---|-------------------------------------------------------------------------------------|-------|------|

7




|   |                                                                                     |       |     |
|---|-------------------------------------------------------------------------------------|-------|-----|
| D |  | M8x35 | 1pc |
| E |  | M8x55 | 1pc |

11




|   |                                                                                       |       |      |
|---|---------------------------------------------------------------------------------------|-------|------|
| B |  | M8x25 | 2pcs |
| E |  | M8x55 | 2pcs |

12



|   |                                                                                       |       |     |
|---|---------------------------------------------------------------------------------------|-------|-----|
| E |  | M8x55 | 1pc |
|---|---------------------------------------------------------------------------------------|-------|-----|


13



|   |                                                                                   |      |
|---|-----------------------------------------------------------------------------------|------|
| A |  | 4pcs |
|---|-----------------------------------------------------------------------------------|------|

M8x16

14




|   |                                                                                   |      |
|---|-----------------------------------------------------------------------------------|------|
| E |  | 4pcs |
|---|-----------------------------------------------------------------------------------|------|

M8x55


⚠ Do not fully tighten the screws yet.

## TYPE 2



1


x2



|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| D |  | 4pcs |
|---|-------------------------------------------------------------------------------------|------|

M8x35

15




|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| E |  | 4pcs |
|---|-------------------------------------------------------------------------------------|------|

M8x55

⚠ Do not fully tighten the screws yet.

16




|   |                                                                                     |      |
|---|-------------------------------------------------------------------------------------|------|
| E |  | 2pcs |
| H |  | 2pcs |

M8x55

8

2

x2




|   |                                                                                       |      |
|---|---------------------------------------------------------------------------------------|------|
| B |  | 4pcs |
| E |  | 4pcs |

M8x25

M8x55

3



|   |                                                                                       |      |
|---|---------------------------------------------------------------------------------------|------|
| E |  | 4pcs |
|---|---------------------------------------------------------------------------------------|------|

M8x55

⚠ Do not fully tighten the screws yet.

13

29

I 48pcs

30

1: Using a drill bit with a diameter of 6, drill mounting holes where installation is required

2: Place the expansion tube into the hole

3: Screw the screw together with the mounting part into the expansion pipe

Z 2pcs

17

D 4pcs

18

E 2pcs

⚠ Do not fully tighten the screws yet.

31

# Finish

Note:Now you can tighten all the bolts.

19

E 2pcs

20

D 4pcs

⚠ Do not fully tighten the screws yet.

21

|   |  |       |      |
|---|--|-------|------|
| C |  | M8x30 | 4pcs |
|---|--|-------|------|

Do not fully tighten the screws yet.

22

|   |  |       |      |
|---|--|-------|------|
| A |  | M8x16 | 1pc  |
| D |  | M8x35 | 2pcs |

25

|   |  |       |      |
|---|--|-------|------|
| F |  | M5x40 | 6pcs |
|---|--|-------|------|

26

|   |  |       |      |
|---|--|-------|------|
| F |  | M5x40 | 3pcs |
|---|--|-------|------|

23

|   |  |       |     |
|---|--|-------|-----|
| A |  | M8x16 | 1pc |
| D |  | M8x35 | 1pc |

Do not fully tighten the screws yet.

24

|   |  |       |      |
|---|--|-------|------|
| E |  | M8x55 | 2pcs |
|---|--|-------|------|

Do not fully tighten the screws yet.

27

|   |  |       |      |
|---|--|-------|------|
| C |  | M8x30 | 4pcs |
|---|--|-------|------|

Fully tighten all the screws.

28

|   |  |        |      |
|---|--|--------|------|
| G |  | ST4x14 | 2pcs |
|---|--|--------|------|