



	A	1	4mm
	B	12	M6*35
	C	12	M6
	D	12	M6*16*1
	E	4	M6




Step 1

Tighten the screws to 80%



Step 2

Tighten all screws.



Step 3

