








Parts




① x 1




② x 1




③ x 1




④ x 1




⑤ x 1




⑥ x 4




⑦ x 1



⑧ x 1




⑨ x 2




⑩ x 1

Hardware




M8x15mm

Ⓐ x26pcs




M8x20mm

Ⓑ x8pcs




M8x30mm


Ⓒ x12pcs




Ⓕ x2pcs




Ⓖ x2pcs



Ⓗ x1pc




Ⓘ x4pcs




M5 ALLEN KEY


Ⓚ x1pc

step 1




C	X12PCS
	
M8X30MM	


step 2




A	X6PCS
	
M8X15MM	

step 3




A	X8PCS
	
M8X15MM	


step 4




A	X4PCS
	
M8X15MM	

step 5




A	X2PCS	B	X4PCS
			
M8X15MM		M8X20MM	

step 6



B	X4PCS
	
M8X20MM	

step 7



A	X6PCS
	
M8X15MM	

step 8

