







ASSEMBLY INSTRUCTION





(A)	10PCS	(B)	6PCS	(C)	8PCS	(D)	4PCS	(E)	2PCS	(F)	2PCS
											
M6x12mm		M6x22mm		M6x30mm		M5x38mm					
(G)	4PCS	(H)	1PC	(I)	1PC	(J)	1PC	(K)	2PCS		
											
Ø4x12mm		M4		M3							


1




C	4PCS
	
M6x30mm	

2





C	4PCS
	
M6x30mm	


3





E	2PCS	F	2PCS
			

4





D	4PCS
	
M5x38mm	

5





(B)	6PCS
M6x22mm	

6



(A)	4PCS
M6x12mm	


7



A X2

A	2PCS
	
M6x12mm	

8





G X2

K


G	2PCS	K	1PC
			
Ø4x12mm			

9



(A)	4PCS	(G)	2PCS	(K)	1PC
					
M6x12mm		Ø4x12mm			

10



Note: This step locks all screws

