


Oliver Chest



Serious or fatal crushing injuries can occur from furniture tipping. To help prevent tipping:

- Never allow children or adults to climb on this furniture
- Never open more than one drawer at a time
- Casters and skids are intended for manufacturing and shipping

purposes only and must be removed from all furniture at installation

If a tipping restraint is not supplied with the furniture, immediately contact the store where the furniture was purchased.

DO NOT INSTALL WITHOUT A TIPPING RESTRAINT.




Use of a tipping restraint may only reduce, but not eliminate the risk of tipping.



KLAIR LIVING


Parts List

P1.	Top	1 pc
P2.	Bottom	1 pc
P3.	Back	2 pcs
P4.	Side	2 pcs
P5.	Back band	1 pc
P6.	Front band	1 pc
P7.	Drawer-Front	4 pcs
P8.	Drawer-Side	8 pcs
P9.	Drawer-Back	4 pcs
P10.	Drawer-Bottom	4 pc.



Hardware List

1. Spreading bolt -----36 pcs
2. Housing 15T -----36 pcs
3. Handle -----4 pcs
4. Handle Screw M4 x 22-----8 pcs
5. Flat Head screw M3.0 x 19-----42 pcs
6. Plastic support -----42 pcs
7. Flat Head screw M3.5 x 15-----56 pcs
8. Flat Head screw M3.5 x 35-----16 pcs
9. Back support-----1 pc
10. Anti-Tip Restraint -----1 set




How to use the **SPREADING BOLT** and **HOUSING**




Pay attention to the direction.


1.




2.




3.




4.




5.




1




2




3




4




5






6





7





8




9




10







12



13



14



BE CAREFUL !



1. Push the ball to the outermost edge of the outer rail.
2. Drawer inner rail butts outer rail, then push it in parallel.
3. After hearing the click sound from both sides, firmly push the drawer in to ensure both drawer rails are installed properly.

15

1



2



3



16

