

Assembly Instruction For Nice 52319
















Tools Recommended

IMPORTANT, RETAIN FOR FUTURE REFERENCE: READ CAREFULLY.

If there are any issues, please contact us by help@arcaliving.com

PART NO.	PARTS	QTY
A		x3
A1	 	x1
A2		x2
G		x6
J		x4
J1		x2
J2		x2
L		x4
U		x4
U1		x4
U2		x4
R		x2
S		x8
W		x1
EE	 ST4.8*15mm	x196

PART NO.	PARTS	QTY
B1		x1
B2		x1
D		x2
F		x6
G3		x2
I1		x4
M		x4
AA	 M6*15mm	x48
BB	 M8*15mm	x32
GG		x16
UU		x16
JJ		x24
LL		x1
MM	 S5	x2
NN	 S4	x2

BOX-3/5


PART NO.	PARTS	QTY
C1		x2
C2		x1
C3		x1
D1		x1
W1		x1


BOX-4/5

PART NO.	PARTS	QTY
E1		x48


BOX-5/5

PART NO.	PARTS	QTY
E1		x44


U1
S
C3
U1
U2
G3
G
U1
U2
B2
C1
U1
U2
G
I1
U2
R
D
G
I1
D1
J2
D
G
I1
G
C1
B1
G3
S
C2
R
J2
A1
F
A2
F
A
F
A2
F
A
F
A
F




A1		x1
W	Adapter	x1




A		x3
A2		x2
F		x6


AA	M6*15mm	x24
NN		




C1		x1
C2		x1
G3		x1
R		x1
S		x4
BB	M8*15mm	x4
GG		x8
MM		




C1		x1
C3		x1
G3		x1
R		x1
S		x4
BB	M8*15mm	x4
GG		x8
MM		




When the gap between the plug and the crossbeam is too small, please Loosen the screws appropriately to adjust the spacing.




MM 







MM





J1		x1
BB	M8*15mm	x4
MM		








J1		x1
BB	M8*15mm	x4
MM		







D		x2
L		x4
LL		



C3
C1
B2
(1)
C1
C2
A1
A2
A2
A
A
A
B2
A1
C3
C3
B2
A1
C3
B2
A1
(2)
C3
B2
A1
A1
B2
x1
MM


C3
B2
C1
B1
C2
C1
A1
A2
A2
A
A
A
(1)
C1
B1
A
C1
B1
A
C1
B1
A
(2)
B1
C2
A
B1
x1
MM





D1		x1
G		x6
AA	M6*15mm	x24
BB	M8*15mm	x12
NN		
MM		






J2		x2
BB	M8*15mm	x4
MM		



A1
B1
C1
B1
A
C1
C3
B2
A1
W
Adapter
W1
W1
x1




U		x4



J		x4	UU		x16
U1		x4	EE		x12
U2		x4	NN		





I1		x4
M		x4
NN		





E1		x92
EE		x184


Done









JJ		x24