




Assembly Instructions





a



2pcs


b



*M6*30*

8pcs


c



*M5*12*

32pcs


d



*M6*15*


18pcs

e




4pcs

f



3pcs


g



*M4*25*


3pcs

h



4pcs

i



*M4*10*


4pcs

n




1pcs

1




$b*8$ $n*1$

2




3



$c*12$ $d*4$ $e*4$ $n*1$


4



$c*4$ $d*1$ $n*1$


5

FRONT




6

SIDE VIEW




7




$d*5$ $n*1$

8




9




$c*12$

10




11




$d*8$ $n*1$

12



13




h/i

$h*4$

$i*4$


14




FRONT

$c*4$

15




16




$f*3$

$g*3$


17




18



19



20



a

$a*2$