





NO	PARTS LIST		QTY
			PSC
A			1
B			1
C			1
D			1
E			1
F			1
G			1
H			1
I		M6*25	12
J		M6*35	4
K		M6*55	4
L		Ø12*Ø6.5*1.0	12
M		Ø16*Ø6.5*1.0	16
N		M6	12
O		4x4	1
P		M6	1
Q			4


Step1




Step2





Step3




Step4




NO	PARTS LIST	QTY	PSC
A		1	
B		1	
C		1	
D		1	
E		1	
F		1	
G		1	
H		1	
I	 M6*25	12	
J	 M6*35	4	
K	 M6*55	4	
L	 Ø12*Ø6.5*1.0	12	
M	 Ø16*Ø6.5*1.0	16	
N	 M6	12	
O	 4x4	1	
P	 M6	1	
Q		4	


Step5




Step6







Step7



Step8



NO	PARTS LIST	QTY PSC
A		1
B		4
C		1
D		1
E	 M6*25	16
F	 Ø12*Ø6.5*1.0	16
G		4
H	 4x4	1

