

Installation & Assembly





Item no.	Reference Image	Description	pcs
A			1
B			2
C			2
D			1

Item no.	Reference Image	Description	pcs
b		M6*30mm	4
c		M6*15mm	8
d		m6	12
e		m6	1

STEP 1


A*1
B*2
b*4
d*4







Do Not Tighten The Screws Completely.

STEP 2




C*2
D*1
c*8
d*8





Do Not Tighten The Screws Completely.


STEP 3



1 | 2


A*1
B*2
b*4
d*4

C*2
c*8
d*8





3

D*1





12x






Do Not Tighten The Ccrews Completely.



Item no.	Reference Image	Description	pcs
N			1
O			1
P			1
K			1
L			1
M			2

Item no.	Reference Image	Description	pcs
a		M6*45mm	2
b		M6*30mm	6
c		M6*15mm	2
d		m6	10
e		m6	1


STEP 1



N*1 O*1
K*1 b*4
c*2 d*4
d*2

Do Not Tighten The Screws Completely.

STEP 2




Do Not Tighten The Screws Completely.

STEP 3


1

N*1
K*1
c*2
d*2




2

0*1
b*4
d*4




3

P*1
b*2
d*2




4

a*2
d*2





5

L*1
M*2





10x





Do Not Tighten The Ccrews Completely.




Item no.	Reference Image	Description	pcs
H			1
I			1
J			1
K			1
L			1
M			2

Item no.	Reference Image	Description	pcs
a		M6*45mm	2
b		M6*30mm	6
c		M6*15mm	2
d		m6	10
e		m6	1

STEP 1


H*1 I*1
K*1 b*4
c*2 d*4
d*2



Do Not Tighten The Screws Completely.


STEP 2

1




J*1
b*2
d*2

2





a*2
d*2



L*1
M*2

3






Do Not Tighten The Screws Completely.

STEP 3


1

H*1
K*1
c*2
d*2




2

I*1
b*4
d*4




3

J*1
b*2
d*2




4


a*2
d*2




5


L*1
M*2





Do Not Tighten The Ccrews Completely.




Item no.	Reference Image	Description	pcs
H			1
Q			1
R			1
K			1
L			1
M			3

Item no.	Reference Image	Description	pcs
a		M6*45mm	2
b		M6*30mm	6
c		M6*15mm	2
d		m6	10
e		m6	1

STEP 1


H*1 Q*1
K*1 b*4
c*2 d*4
d*2



Do Not Tighten The Screws Completely.

STEP 2


1




R*1
b*2
d*2

2


a*2
d*2





L*1
M*3

3




Do Not Tighten The Screws Completely.

STEP 3


1

H*1
K*1
c*2
d*2




2

Q*1
b*4
d*4




3

R*1
b*2
d*2




4

a*2
d*2





5

L*1
M*3




10x






Do Not Tighten The Ccrews Completely.




Item no.	Reference Image	Description	pcs
E			1
F			4
G			1


Item no.	Reference Image	Description	pcs
c		M6*15mm	12
d		m6	12
e		m6	1

STEP 1






STEP 2



E*1　G*1
F*4
c*12
d*12



Do Not Tighten The Ccrews Completely.