




OWNER'S MANUAL




(1) Cover




(2) Gearloft 3 pcs



(3) Main iron pipe 20 pcs




(4) Cross iron pipe 9 pcs



(5) Steel Stakes 4pcs



(6) 4-way PVC fittings 4 pcs




(7) 3-way PVC fittings 8 pcs



(8) Reusable Cable Ties 5 pcs


Step 1

Take 3-way & 4-way PVC Fittings and the main iron pipe, assemble the bracket according to the following diagram.




Step 3

Place the assembled bracket flat to attach the cover and zip up.




Step 4

Insert the cross pole into the sleeve of gearloft, 3 pcs in total. Fix Cross pole to main bracket from 45 degree angle, which make it more easy. The middle screw in main pipe prevents the cross pole sliding. Fix the quick clips to main bracket.



High Attention on Step 2 ★★★★★

Tighten each pipe into the fittings from top to bottom, which saves effort and ensures pipes pressed in place. After pressing one side, flip it over to the other side and continue to press each pipe. Make sure the frame stable and sturdy, which make it easier to fit the cloth cover.



Step 5

Metal stakes are optional. Please maintain a 45 degree position to strike the stakes downwards if required. Perfect finished.

