














Assembly Instructions















Exploded view




















Component parts supplied


Ref	Dimensions	Visual	Qty
1	1145*470*24		1
2	332*398*15		2
3	720*400*15		1
4	720*400*15		1
5	720*400*15		1
6	720*400*15		1
7	332*70*15		2
8	330*345*12		2
9	332*90*15		4
10	645*342*5		2
11	1285*470*24		1
12	720*280*15		1
13	720*280*15		1
14	1137*280*12		1
15	832*280*12		1
16	900*230*15		2
17/18	900*230*15		2


Ref	Dimensions	Visual	Qty
19	283*208*12		4
20	280*205*12		2
21	360*181*15		2
22/23	350*130*12		4
24	282*130*12		2
25	348*292*5		2
26	1275*266*24		1
27	609*228*15		1
28	609*209*15		1
29	250.5*208*12		2
30	235*58*15		2
31	607*58*15		1
32	900*40*15		4
33	617*452*5		1
34	910*291*5		2
35	600*205*15		1
36	465*360*15		2

Parts and fittings


A ×102  M6×35mm	B ×102  Φ15*10mm	C ×2  Ø3.5*14mm
D ×75  Φ8*30mm	E ×20 	F ×1  M4
G ×6  孔距128mm	H ×4  M4*18mm	J ×8  M4*16mm
L ×42  Φ3*14mm	M ×1 	N ×4  7*50mm
O ×1  200mm	P ×4  M6*12mm	Q ×6 
R ×36  Φ4*14mm	S ×8  Φ4*35mm	T ×4  M6*20mm
U ×16 	V ×1 	CL ×2  350mm
CR ×2  350mm	DL ×2  350mm	DR ×2  350mm


Step 1







×2







×2








Step 2



Ⓐ ×8




Ⓛ ×6




Ⓓ ×4




Ⓒⓛ ×1





Ⓒⓡ ×1





Please fasten the screws through these holes for this step





















Step 3





Please fasten the screws through these holes for this step





































Step 4



















Step 5






















Step 6



















Step 7

























Step 8
















Step 9





















Step 10










Step 11











Step 12
















Step 13


















Step 14



A × 20



B × 8



B
B
B
B
B
B
B
B
28
27
17
18

28
27






A
A
A
A
32
A
A
16
×4
×2



1
2
Arrow
3
Tighten





Step 15


















Step 16














Step 17


















Step 18






Step 19








Step 20

Ⓐ × 15




Ⓓ × 2



Ⓡ × 4




Ⓖ × 2





Ⓙ × 4





Ⓠ × 2




















Step 21

Team Lift










Step 22


Ⓑ × 7







Step 23











Step 24



















Step 25









































Please fasten the screws through these holes for this step









Step 26

G ×2




H ×4




R ×24





Q ×4







X2








Step 27





Step 28

