




ASSEMBLY INSTRUCTION






1



X1

2




X1

3




X1

4




X1

5



X4

A




M6*12mm
X12+1

B




X8+1

C




X4

D



M4
X1




1



x 4


C x 4

2




A x 4

3






B x 4

4




5




A x 8

6



B x 4

7



8

