

























Disassembly and installation of accessories




A 36+3  Ø6*35mm	B 36+3  Ø15*11.5mm	C 12  Ø8*40mm	D 72+3  M3.5*12mm	E 24  M4*25mm	F 72+2  M4*40mm	G 72+2  Ø10*10mm
H 48 	I 26  M6*20mm	J 3 	K 48+2  M3.5*16mm	L 8  M6*40mm	M 12  M ₁ M ₂ 14"	N 2  M6*35mm
O 10  M4*50mm	P 8  M6*12mm					




1  1PCS	2  1PCS	3  1PCS	4  1PCS
5  2PCS	6  3PCS	7  1PCS	8  1PCS
9  1PCS	10  6PCS	11  12PCS	12  6PCS
13  6PCS	14  6PCS	15  6PCS	16  6PCS
17  6PCS	18  1PCS	19  2PCS	20  2PCS

STEP 1






STEP 2






STEP 3

Make sure the screws are loose
before pressing




A	36PCS
	
Ø6*35mm	



STEP 4



D	12	M	4
			
M3.5*12mm			




STEP 5





X2

D	24	M	8
			
M3.5*12mm			





STEP 6




B	4
	
Ø15*11.5mm	

STEP 7





B	4	C	4
			
Ø15*11.5mm		Ø8*40mm	

STEP 8



J	3
	


STEP 9



B	4
	
Ø15*11.5mm	


Note:
Far from the edge;
close to the inside

STEP 10




B 10	C 2
Ø15*11.5mm	Ø8*40mm

STEP 11




B 10	C 2
Ø15*11.5mm	Ø8*40mm

STEP 12



B 4	C 4
	
Ø15*11.5mm	Ø8*40mm

STEP 13



I 8

M6*20mm



STEP 14

D

M₂

D*3

M₂*1

12 X6

13 X6

D 36	M 12
M3.5*12mm	

--	--	--	--	--

STEP 15

12

14

17

13

16

F

G

F*6

G*6

X6

F 36	G 36
M4*40mm	Ø10*10mm

--	--	--	--	--

STEP 16

15

F

G

K

H

F*6

G*6

H*6

K*6

180°

X6

F 36	G 36	K 36	H 36
M4*40mm	Ø10*10mm	M3.5*16mm	

--	--	--	--	--

STEP 17

E*4

10

11

11

10

I*3

E	24
M4*25mm	

I	18
M6*20mm	


X6

STEP 18


M1

M2


Note: align M1 with M2 and push it in



STEP 19




H*12
K*12



K	12
	
M3.5*16mm	

H	12
	



STEP 20

