





Assembly Instruction






 Hammer and Screwdriver
 are not included !!



1 OF 6


NO.	QTY.	LINEDRAWING
(A)	6	
(B)	4	
(C)	20	
(D)	20	
(E)	12	 8x40
(F)	1	
(G)	4	 3.5x35
(H)	44	 3.5x14
(I)	18	 3.5x12
(J)	3	
(K)	22	 
(L)	24	 $\phi 20$
(M)	4	 M6x30
(N)	2	   
(O)	1	
(P)	1	
(Q)	1	
(R)	2	

PARTS LIST




NO.	QTY.
①	1
②	1
③	1
④	1
⑤	1
⑥	2
⑦	2
⑧	1
⑨	1
⑩	1
⑪	1
⑫	2
⑬	1
⑭	2
⑮	2
⑯	1

1




F		H		R	
	1x		8x		2x

2




E		8x40
	4x	
C		12x
D		12x

3



E		8x40
	4x	
C		4x
D		4x

4




0



1x

5




B



4x

6



H




4x

K



22x

7



H



4x

M



M6x30


4x

P



4 OF 6

8



G


4x

E


8x40

4x

9



10




C

4x

D

4x

11




F

1x

H


4x

12




A		I		J	
	6x		16x		2x

13



Q	
	1x




14



H	
	24x

15

I		2x
L	 $\phi 20$	24x
		1x
N		2x



6 OF 6