















Assembly instruction (F / Q)











Assembly instruction (F / Q)



① x1 	② x4 	③ x1 
④ x1 	⑤ x4 	⑥ x2 
⑦ x4 	⑧ x2 	⑨ x1 
⑩ x2 	⑪ x6 	⑫ x28 
⑬ x2 	⑭ x2 	


Hardware List

A×24 (2+extra)  M8×60mm	B×14(1+extra)  M6×50mm	C×12(1+extra)  M6×40mm
D×15 (1+extra)  M6×35mm	E×16 (1+extra)  M6×15mm	F×24 (2+extra)  M6×10mm
G×13 (1+extra)  M6×15mm	H×2  M4	I×2 
J×2  M8×40mm	K×2  M5×40mm	

1



A×8pcs



M8×60mm

E×4pcs




M6×15mm

F×8pcs




Ø18*Ø8.5*1.5T




x 2

2



D×4pcs




M6×35mm

G×4pcs



M6×15mm




x 2

3




B×6pcs




M6×50mm

D×6pcs



M6×35mm



x 2


4





E×4pcs








M6×15mm





x 2




A×8pcs
 M8×60mm
B×2pcs
 M6×50mm
F×8pcs
 Ø18*Ø8.5*1.5T
I×2pcs





A×8pcs
 M8×60mm
B×1pc
 M6×50mm
F×8pcs
 Ø18*Ø8.5*1.5T


7




C×12pcs



M6×40mm



8



E×8pcs




M6×15mm



G×8pcs



M6×15mm



9




B×1pc



M6×50mm

D×5pcs






M6×35mm

G×1pc



M6×15mm


10





11





B×4pcs



M6×50mm



12



J×2pcs



M8×40mm

K×2pcs



M5×40mm

Tighten all screws 100%