








ASSEMBLY INTRODUCTION




Exploded View




Fittings

 A x 58 M6 x 35 mm	 B x 58 φ15 x 9.5 mm	 C x 18 φ6 x 30 mm	 D x 32 φ4 x 35 mm	 E x 72 φ3 x 12mm
 F x 5 φ6 x 50 mm	 G x 2 35 x 35 mm	 H x 4 φ4 x 12 mm	 I x 2 φ6 x 30 mm	 J x 2 φ4 x 40 mm
 K x 12	 CL x 6 300 mm	 CR x 6 300 mm	 DL x 6 300 mm	 DR x 6 300 mm






Step 1





Step 2






Step 3




Step 4






Step 5




Step 6





Step 7






Step 8




Step 9






Step 10







Step 11



Step 12





Step 13





Step 14

x6




Step 15

x6




Step 16




x6




Step 17
x6




Step 18
x6



E x 36
x 12 mm




DL x 6
300 mm



DR x 6
300 mm

Step 19



Step 20

