




ASSEMBLY INTRODUCTION



Exploded View




Fitting



Ax35(+2)
Ø6x35mm



Bx35(+2)
Ø15x10mm




Cx41(+2)
Ø6x30mm



Dx7(+1)
Ø4x35mm



Ex48(+2)
Ø3.5x12mm



Fx6(+1)
Ø4x50mm




Gx8



Hx8




Ix4




Jx4



Kx16(+1)
Ø3x16mm





Lx2
Ø4x14mm





Mx2
Ø6x30mm


Step 1




Step 2



Step 3





Bx8




Cx4

Step 4




Ax4

Step 5





Bx8





Cx2

Step 6





Cx10


Step 7




Step 8




Step 9





Step 10



Step 11





Step 12




Cx10

Step 13




Ax6

Step 14



Bx6

Step 15




Gx8

Step 16


 Ex8

 Hx4


 Ix4





Step 17






 Ex16




Step 18



Step 19



Step 20



Step 21

