




ASSEMBLY INTRODUCTION



Plate




Plate



Fitting

A x 41 +2




M6 x 35 mm

B x 41 +2




φ15 x 9.5 mm

C x 49 +2



φ6 x 30 mm

D x 13 +1



φ4 x 30 mm

E x 18 +2




φ3 x 12mm

F x 3



32 x 32 x 25 mm

G x 3




φ4 x 20mm

H x 6



26 mm

I x 8




φ6 x 12 mm


J x 16 +2



K x 1




L x 24



φ4 x 14mm

M x 2



N x 4



O x 6




φ7 x 50 mm

P x 1




4 mm

Q x 1



CR x 2




300 mm

CL x 2




300 mm

DR x 2



300 mm


DL x 2



300 mm

1

A x 9




2

C x 1



D x 2



3


B x 1



C x 4



D x 1




4


B x 4





C x 6





5




6



7




8



9

A x 8



10


C x 4



O x 4




P x 1



11

A x 4




12

B x 4




C x 2



13


A x 2



E x 2




CR x 1



14


C x 4





O x 4





P x 1





15






16




17




18





19





20




21





22






24





25

I x 8




26



D x 8





27





28




29




30



31



32



E x 2




K x 1





33






J x 16



34

N x 4







**Customer Attention:**



To align doors and control gap in between doors. Product doors may need adjusting during and after assembly.

This can be done by adjusting appropriate screws. See below illustration.



**Vertical Door Adjustment:**

Loosen both screws on all hinges and lift the door to the desired height.

This allows an even space at the top and bottom between the door and frame.

**Lateral Door Adjustment:**

If door is hinge bound, (rubbing on frame as you close or open door) loosening screw shown and move the door in appropriate direction. (In or out)

**Horizontal Door Adjustment:**

Rotate Screw clockwise or anticlockwise. This will produce an even gap between doors and frame.