


















INSTRUCTION MANUAL














Supplied Parts and Hardware

Attention: Do not tighten the screws until all of them are in right positions


1  775*435*20mm X 1	2  775*435*20mm X 1	3  1250*480*15mm X 1	4  703*435*15mm X 1
5  703*435*15mm X 1	6  545*435*12mm X 1	7  435*300*12mm X 1	8  435*300*12mm X 1
9  375*300*12mm X 2	10  532*304*3mm X 2	11  520*295*15mm X 2	12  1175*435*12mm X 1
13  300*20*20mm X 4	14  545*20*20mm X 2	15  1175*30*20mm X 2	

Supplied Parts and Hardware

Attention: Do not tighten the screws until all of them are in right positions



A  M6*40 x 34	B  M6*38 x 24	C  x8	D  M6*28 x12
E  M4*18 x 4	F  x 2	G  x 4	L  (L1)  (L2) x 2
M  M4*12 x 6	N  x 1	 x 1	 x 1

Step 1




(A)x3

Step 2




(A)x3

Step 3



 (A)x4



Step 4



 (B)x8

Step 5



Please tighten the screws by 80%



Ⓑx2


Step 6

Please tighten the screws by 80%






Ⓑx2

Step 7




Step 8

Please tighten the screws by 100%




A x12

Step 9



 **A**x12

Step 10




 **M**x4

 **L1**x2


 **C**x8

Step 11




 (B)x8

Step 12





 (B)x4

Step 13



 **D**x12

Step 14




 **G**x4


 **F**x2

 **E**x4



Step 15



Step 16



Step 17



Step 18

