











ASSEMBLY INSTRUCTION




Loosely hand-tighten screws when fitting the table base; fully tighten all only after the full frame is aligned and assembled.

If you have any questions, please feel free to contact us at any time.


Parts & Tool List

① x2 	② x1 	③ x2 	④ x4 	⑤ x2 
⑥ x2 	⑦ x2 	⑧x1 		
A x16+1  M6*70mm	B x10+1  M6*60mm	C x6+1  M6*25mm	Dx12+1  M6*12mm	Ex2  S4


1



× 2



Cx4




Bx4




Ex2

2






Dx4




Ex1


3



× 2





Dx8




Ex1

4






Ax8





Ex1

5


Screw holes face upward









6




7

Notice：keep all the screws 50% tightness first , then Push the 1&2 desktop，make sure no gap , then tighten the screws





8



9

