







BC015

Assembly Instructions




Assembly Instructions

$\varnothing 15 \times 12$  A x 44	$\varnothing 7 \times 38$  B x 44	$\varnothing 8 \times 30$  C x 25	$\varnothing 7 \times 48$  D x 14	4MM  E x 1
103*25*12  F x 1	M4x20  G x 2	 H x 14	 I x 6	$\varnothing 4 \times 14$  J x 4
656*16*20  K x 1	M6x25  L x 2	M4x18+ $\varnothing 10 \times 10$  M x 2	118*20*18  N x 2	M6x18  O x 4
62*26*2  P x 2	$\varnothing 6 \times 30$  Q x 22			




STEP 1

Ax2
Bx2
Kx1
Lx2




STEP 2

Ax6
Bx6




STEP 3

Ax10
Bx10
Cx8




STEP 4

Qx12




STEP 5

Ax2
Bx2
Cx5
Qx6




STEP 6

Cx8
Dx14
Ex1
Qx4




STEP 7

Ax11
Bx11




STEP 8

Ax7
Bx7




STEP 9

Ix6




STEP 10




STEP 11

Ax6
Bx6
Cx4




STEP 12

Hx14




STEP 13

Fx1
Gx2
Jx4
Nx2
Ox4
Px2




STEP 14




STEP 15

Mx2



STEP 16



FINISH