




















ASSEMBLY INSTRUCTION











Part List

A  (1 pc)	B  (2 pcs)	C  (2 pcs)	D  (1 pc)
E  (4 pcs)	F  (2 pcs)	G  (1 pc)	H  (1 pc)
I  (1 pc)	J  (1 pc)	K  (1 pc)	L  (1 pc)
M  (2 pcs)	N  (1 pc)	O  (4 pcs)	P  (4 pcs)
Q  (4 pcs)	R  (1 pc)	S  (1 pc)	T  (1 pc)


Hardware List

1  M6x45 (12 pcs)	2  M6x50 (2 pcs)	3  M6x80 (18 pcs)
4  M8x50 (4 pcs)	5  Ø8.5x20 (4 pcs)	6  Ø8.5x20 (4 pcs)
7  Allen key 4 (4 pcs)		


CARTON CONTENT:



B (2 pcs)




C (2 pcs)




E (4 pcs)




F (2 pcs)




P (4 pcs)




Q (4 pcs)




S (1 pc)




A (1 pc)




D (1 pc)




G (1 pc)




H (1 pc)




I (1 pc)




J (1 pc)




K (1 pc)



L (1 pc)




M (2 pcs)




N (1 pc)




O (4 pcs)



R (1 pc)



T (1 pc)




Hardware

STEP1: Following below illustration.

3



6pcs




STEP2: Following below illustration.

2




1pc



STEP3: Following below illustration.


1



4pcs

STEP4: Following below illustration.


3



6pcs

STEP5: Following below illustration.


2



1pc

STEP6: Following below illustration.

1



4pcs

STEP7: Following below illustration.


3

6pcs


STEP8: Following below illustration.

1

4pcs




STEP9: Following below illustration.



4	
	4pcs
5	
	4pcs
6	
	4pcs

STEP10: Following below illustration.



FINISH:

