






Parts




H X 1




I X 1




J X 1



K X 1



L L X 1 L R X 1



M X 1

Hardware



spare part

A X 2



M6*25

B X 4



C X 4



4#

D X 1



M6*16

E X 4



M8*16


F X 4




5#

G X 1


1



2



3



4

