







ASSEMBLY INSTRUCTION


A	B	C	D	E	I	J
 X02	 X08	 X10	 X10	 X01	 Left X01	 Right X01
F	G	H				
 X01	 X01	 X01				

STEP 1.




Note: Don't turn all screw completely.
Turning 70% is enough in this phase.

STEP 2.



STEP 3.

Note: Adjust four legs to keep them at the same level.
Then turn all screws correctly



STEP 4.

