

12th Step: Connect the tree topper with fifth pole together

↑

11th step:Place smallest Layer(15") on the pole

↑

10th Step: Connect the smallest tips Pole with forth pole together

↑

9th step:Place Layer(18") on the pole

↑

8th Step: Connect the second smaller tips Pole with third pole together

↑

7th step:Place third Layer(21") on the pole

↑

6th Step: Connect the third longer tips Pole with second pole together

↑

5th step:Place second Layer (26") on the pole

↑

4th Step: Connect the second longer tips Pole with first pole together

↑

3rd step:Place First Layer (32") on the pole

↑

2nd step:Connect the longest tips Pole with metal base

↑

1st step：
set up Tree Base